Assembly Proce	dure WEBSITE VIDEO No.		Electrical S	pecif	icatio	<u>n</u>		DO	NOT SCALE DRAWING	DATA SHEE	T SHEET 1 O
 Place Nut and Clamp sle cable. Trim cable to dimensions Ensure centre conductor damaged. Tin centre conductor. 2. With the braid fanned out 	Impedance:CABLE DEPENDENTFrequency:TBADielectric W/V:TBAInsulation res:TBAMechanical SpecificationCentre contact retention				DENT	Ø14.5					
smaller tapered end of To contact over cable dielect - Push the Top Hat firmly h up to the cable jacket. En that the smaller diameter taper passes between the dielectric and braid.	Axial Force: Cable Retention Mating cycles	ntion: TBA les: 100							Ø3.9		
 Wrap the fanned out Brail Place the Connectors Sm 	Environmental Specification						Ø	<i>4</i> 0%			
Insulator over the cable			Operating Ter	np:	TBA					₩ 4.9 ₩	Ηİ
dielectric, and inside courbore of Top Hat Contact, trapping braid. Note orier 3.	Tooling Centre Contac	Tooling Centre Contact: SOLDER						H			
	COAX Tool No):						5.6	► A/F		
 Place contact on Tinned centre conductor. Ensure centre conductor is visible in the inspection 			Crimp Sleeve: COAX Tool No								HEX 11
 hole in centre contact. Heat centre contact so th the solder melts, adding additional as required. Care should be taken not to overheat the contact. Allow to cool. 4. Carefully place contact th sub-assembly into Conne. Ensure contact is seated in front insulator. Slide Clamp sleeve forwar rear of Top Hat Contact. 	his ector body in place ard up to	-0.910				P				a = 4.0 mm b = 7.0 mm c = 7.0 mm d = 3.0 mm	
 Slide Nut forward and en Using a suitable spanner 		3				9	COUPLING NUT	ZINC	NICKEL		
Connector body Tighten nut to clamp cable.								8	CABLE CLAMP	SILICONE	N/A
- Check assembly.						7	REAR INSULATOR	PTFE	N/A		
	COAX CONNECTORS LTD 6-8 COLNE ROAD, TWICKENHAM, MIDDLESEX. TW1 4JR		REVISION DA00	A4	DIMENSIONS ARE IN			6	CENTRE CONTACT	BRASS	GOLD
				DRAWN	NAME GE	SIGNATURE	DATE 05/02/2010	5	FRONT INSULATOR	PTFE	N/A
0 0 ALVI		лс		CHK'D	PSK		17/02/2010	4	WASHER	Fe	NICKEL
GUAX	Description	BNC CLAMP PLUG	RG59/URM 70	APPV'D			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	3	SPRING & RETAINING RING	SK5	NICKEL
	20001000		, 0			GIVEN AS AN INDIC		2	FRONT GASKET	RUBBER	N/A
	Part Number	Part Number 10-001-A0-A1			AND IS SUBJECT TO CHANGE WITHOUT NOTICE. IN THE CONTINUAL GOAL TO IMPROVE OUR PRODUCTS, WE RESERVE THE RIGHT TO MAKE ANY		1	BODY, TOP HAT CONTACT, NUT	BRASS	NICKEL	
				MODIFICA				ITEM	DESCRIPTION	MATERIAL	

Email: info@coax-connectors.com